

PLANTA: MX18 - Nacobre San Luis
PEDIDO/ORDER:

CLIENTE/CUSTOMER: PEDIDO CLIENTE/P.O.: PEDIDO / ORDER: NORMA/STANDAR: NORMA CTE./CUST. SPEC.: PARTE CTE./CUST. PART:	TUMATSA S.A DE C.V. NMX-W-101/1-2002	PRODUCTO/PRODUCT: DESCRIPCIÓN/DESCRIPTION: ALEACIÓN/ALLOY: TEMPLE/TEMPLER: PESO NETO/NET WEIGHT: TIPO DE PARED / WT: CANTIDAD / QUANTITY:	CODO A 90° DE 3/4" CATALOGO 107-19 C12200 RIGIDO H58
---	---	--	---

**COMPOSICIÓN QUÍMICA REQUERIDA
CHEMICAL COMPOSITION REQUIRED**


ELEMENTO	c	Fe	Mn	Ni	P	Pb	S	Zn	Cu
Max %					0.040				99.9900
Min %					0.015				

**No. DE MUESTRA
HEAT NUMBER
Colada**
**COMPOSICION QUIMICA DETERMINADA
CHEMICAL COMPOSITION DETERMINED**

					0.0180				99.9900
--	--	--	--	--	--------	--	--	--	---------

PRUEBAS FÍSICAS / MECÁNICAS. PHYSICAL / MECHANICAL PROPIETIES

PRUEBA / TEST	U/M	REQUERIDO / REQUIRED	
		Mínima / Minimum	Máxima / Maximum
RESISTENCIA A LA TENSION	KSI		----
LIMITE ELASTICO	KSI		----
DUREZA	HR30T	53	52.000
EDDY CURRENTS TEST			

ORDEN / ORDER:
LOTE / BATCH:
Entrega / Delivery:
**OBSERVACIONES
CODO DE 3/4" 107-19**

RAUL VILLAFUERTE GONZALEZ
**REVISO: CALIDAD
REVIEWED: QUALITY**
**HECHO EN MEXICO
MADE IN MEXICO**
NACIONAL DE COBRE S.A. DE C.V. CERTIFICA QUE EL MATERIAL EMBARCADO BAJO ESTA ORDEN HA SIDO INSPECCIONADO, PROBADO Y ENCONTRADO CONFORME A LA ESPECIFICACIÓN APLICABLE.
A NUESTROS ARCHIVOS SE ENCUENTRAN REPORTES DE PRUEBA SUJETOS A EXAMEN.
SE PROHIBE LA REPRODUCCION TOTAL O PARCIAL DE ESTE CERTIFICADO SIN LA AUTORIZACION DE LA GERENCIA DE CALIDAD.
NACIONAL DE COBRE, HERE BY CERTIFIES THAT MATERIAL SHIPPED UNDER THIS ORDER HAS BEEN INSPECTED, AND FOUND IN AGREEMENT WITH APPLICABLE SPECIFICATION, TEST REPORTS ARE ON FILE SUBJECT TO EXAMINATION.
TOTAL OR PARTIAL REPRODUCTION OF THIS CERTIFICATE IS NOT ALLOWED WITHOUT AUTORIZATION FROM THE QUALITY MANAGER.
THE COUNTRY OF ORIGIN OF THE CAST MATERIAL FOR THIS ORDER WAS MEXICO.